UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

ORIGINAL

FIELD NOTES

OF

THE DEPENDENT RESURVEY OF

A PORTION OF THE WEST BOUNDARY,

A PORTION OF THE SUBDIVISIONAL LINES,

A PORTION OF THE SUBDIVISION OF SECTION 30,

THE RETRACEMENT OF TRACT 37

AND

THE SUBDIVISION OF A PORTION OF SECTION 30,

ΙN

TOWNSHIP 34 SOUTH RANGE 5 WEST

OF THE SALT LAKE MERIDIAN IN THE STATE OF UTAH

EXECUTED BY

Jeremy D. Davis Cadastral Surveyor

Under special instructions dated **August 8**, **2008**, approved **August 8**, **2008**, which provided for the surveys included under Group Number **1082**, and assignment instructions dated **August 8**, **2008**.

Survey commenced August 19, 2008 Survey completed August 28, 2008 TOWNSHIP 34 SOUTH, RANGE 5 WEST, SALT LAKE MERIDIAN, UTAH

The following field notes are those of the dependent resurvey of a portion of the west boundary, a portion of the subdivisional lines, a portion of the subdivision of section 30, the retracement of tract 37 and the subdivision of a portion of section 30, in T. 34 S., R. 5 W., Salt Lake Meridian, Utah.

History of Surveys

	Surveyed by		Retr. or Resurveyed by				
SOUTH BOUNDARY							
All Portion All Portion	T.C. Bailey	1874	A. Nelson C.P. Sylvester M.H. Krohn	1924 1972 1987			
EAST BOUNDARY (Panguitch Guide Meridian)							
All	J. G. Burrill	1874					
WEST BOUNDARY							
All Portion	T.C. Bailey & J.G. Burrill	1874	A. Nelson	1924			
NORTH BOU	JNDARY						
All Portion	T.C. Bailey & J.G. Burrill	1874	C.P. Sylvester	1978			
SUBDIVIS	ION						
All Portion Portion	T.C. Bailey & J.G. Burrill	1874	A. Nelson M.H. Krohn	1924 1987			
TRACT 37							
All	A. Nelson	1924					

COUNTY SURVEYS

The Garfield County Surveyors Office has monumented some corners in the township, with Corner Perpetuations and Filing Records on file in the Garfield County Recorder's Office.

PRIVATE SURVEYS

A survey was executed by Kary B. Monroe, P.L.S. 164561, with a plat dated February 22, 1999, on record at the Garfield County Recorder's Office.

A survey was executed by Lanny K. Talbot, R.P.L.S. 165634, with plats dated October 26, 2000 and February 18, 2001, on record at the Garfield County Recorder's Office.

INDEX DIAGRAM

Township 34 South, Range 5 West

6	5	4	3	2	1
7	8	9	10	11	12
18 13	17	16	15	14	13
5 19	12 20	21	22	23	24
3 30	8 29	28	27	26	25
31	32	33	34	35	36

The	Resurvey of	the Su	ubdivisio	n of	Sectio	n 30	 		 	• • • • :	14
The	Retracement	of Tra	act 37				 		 		17
The	Survey of tl	he Subc	division	of S	ection	30	 	. .	 		19

T. 34 S., R. 5 W., SALT LAKE MERIDIAN, UTAH

A survey was executed by James A. Raines, P.L.S. 334569, with a plat dated July 27, 2007, on record at the Garfield County Recorder's Office.

This survey was executed in accordance with the specifications set forth in the Manual of Surveying Instructions, 1973, and the Special Instructions for Group No. 1082, dated August 8, 2008.

The direction of the lines was determined by references to true meridians, established by Global Positioning System (GPS) utilizing Real-Time Kinematic (RTK) techniques throughout the survey. The positional accuracy of this survey complies with the Standards and Guidelines for Cadastral Surveys Using Global Positioning System Methods, dated May 9, 2001. Trimble model 5800 GPS receivers were used for field collection. Cadastral Measurement Management (CMM) software was the primary software utilized for project calculations.

Preliminary to the resurvey, the lines of the prior surveys were retraced and search was made for all corners and their calls of record. Identified corners were remonumented in their original positions. Lost corners were reestablished and remonumented at proportionate positions based on the official record. The retracement data was thoroughly verified and only the true line field notes are given herein.

Geodetic control was derived from National Geodetic Survey Station "Panguitch" with the published data as follows:

Latitude: 37°48'58.37061"N. Longitude: 112°24'20.17241"W. NAD 1983 (1994). NAVD 1988 Elevation, 6802 feet.

The geographic position of the corner of sections 29, 30, 31 and 32, as determined by using indirect RTK methods from National Geodetic Survey Station "Panguitch" is as follows:

Latitude: 37°49'04.630" N. Longitude: 112°27'03.000" W. NAD 1983.

Network Accuracy = 0.200 meters at 95% confidence.

CHAINS

Dependent Resurvey of a Portion of the West Boundary, T. 34 S., R. 5 W., Salt Lake Meridian, Utah.

Reestablishment of the Survey Executed by T.C. Bailey and J.G. Burrill in 1874, and the Resurvey Executed by A. Nelson in 1924.

Beginning at the corner of sections 25, 30, 31, and 36, monumented with a Garfield County Survey monument, an aluminum pipe, 2 inches diameter, firmly set, projecting 2 inches above the ground with a 3 1/4 inches diameter aluminum cap marked:

Garfield County T34S R6W R5W S25 S30 S36 S31 2006 PLS 161040

No remaining evidence of the 1924 bearing trees was found.

Found a steel fence post alongside the aluminum post.

This monument as set by Garfield County in 2006, is accepted as the best available evidence of the position of the original section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

Corner falls in a flat open meadow.

 $N.0^{\circ}05.8'$ E., between sections 25 and 30.

19.580 The S 1/16 section corner of sections 25 and 30, monumented with a Garfield County Survey monument, an aluminum pipe, 2 inches diameter, firmly set, with a 3 1/4 inches diameter aluminum cap marked:

Garfield County
T34S
S 1/16
R6W R5W
S25 S30
2006
PLS 161040

Found a mound of stone, south of the aluminum pipe.

Found a steel fence post alongside the aluminum pipe.

CHAINS

This monument as set by Garfield County in 2006, is accepted as the best available evidence of the position of the S 1/16 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

Corner falls on flat ground in piñon growth.

N. $0^{\circ}06.4'$ E., beginning new measurement.

19.557 The 1/4 section corner of sections 25 and 30, monumented with a volcanic stone, 20x4x4 inches, firmly set, in an embedded mound of stone, marked 1/4 on west face.

No remaining evidence of the 1924 bearing tree was found.

Found a steel fence post 1.6 ft. south of marked stone.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 20 inches in the ground, to solid rock, in a mound of stone 4 ft. base to top, with aluminum cap marked:

T34S R6W R5W 1/4 S25|S30 2008

Deposit the marked stone alongside the aluminum post.

Deposit a magnet enclosed in a plastic case at the base of the aluminum post.

Corner falls on flat ground in sagebrush and scattering piñon and juniper growth.

N. 0°24.0' E., beginning new measurement.

40.725 The corner of sections 19, 24, 25, and 30, monumented with a trachyte stone, 16x10x6 inches, firmly set, in a mound of stone, 3 ft. base, marked 2 grooves on south, 4 grooves on north faces, and 6 notches on east and west edges.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:

CHAINS

T34S R6W R5W S24 S19 S25 S30 2008

Deposit the marked stone alongside the aluminum post.

Deposit a magnet enclosed in a plastic case at the base of the aluminum post.

Set a steel fence post alongside the aluminum post.

Corner falls on a gradual north slope in scattering piñon growth.

Reestablishment of the Survey Executed by T.C. Bailey and J.G. Burrill in 1874.

N. $0^{\circ}48.4'$ E., between sections 19 and 24.

39.895 The 1/4 section corner of sections 19 and 24, monumented with a trachyte stone, 8x8x4 inches, firmly set, marked 1/4 on west face. (Record, Sandstone, 14x8x6 inches.)

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with aluminum cap marked:

T34S R6W R5W 1/4 S24|S19 2008

Deposit the marked stone alongside the aluminum post.

Deposit a magnet enclosed in a plastic case at the base of the aluminum post.

Set a steel fence post alongside the aluminum post.

Corner falls on a gradual southeast slope in piñon growth.

N. 0°28.5' E., beginning new measurement.

39.735 The corner of sections 13, 18, 19, and 24, monumented with a Talbot Land Surveying monument, an aluminum pipe, 2 1/2 inches diameter, firmly set, projecting 2 inches above the ground, with a 3 1/4 inch diameter aluminum cap marked:

CHAINS

from which the 1874 bearing trees

A piñon, 10 ins. diam., bears N. 40° E., 53 links distance, with no visible scribe marks on an open blaze. (Record, $N.44^{\circ}E.$, 52 links distance.)

A piñon, 10 ins. diam., bears S. 79° E., 43 links distance, with no visible scribe marks on a mostly healed blaze. (Record, 42 links distance.)

No remaining evidence of the SW or NW bearing trees were found.

Found a steel fence post 1.6 ft. north the aluminum pipe.

This monument as set by Lanny Talbot in 2003, is accepted as the best available evidence of the position of the original section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

Corner falls on flat ground in piñon growth.

Dependent Resurvey of a Portion of the Subdivisional lines, T. 34 S., R. 5 W., Salt Lake Meridian, Utah.

Reestablishment of the Survey Executed by T.C. Bailey and J.G. Burrill in 1874, and the Resurvey Executed by A. Nelson in 1924.

From the corner of sections 19, 24, 25, and 30, on the west boundary of the township, hereinbefore described.

N. 89°52.6' E., between sections 19 and 30.

39.916 The 1/4 section corner of sections 19 and 30, monumented with a Garfield County Survey monument, an aluminum pipe, 2 inches diameter, firmly set, projecting 2 inches above the ground with a 3 1/4 inches diameter aluminum cap marked:

CHAINS

Found a mound of stone 3 ft. by 3 ft. base by 3 ft. high, north of the aluminum pipe.

Found a steel fence post 0.50 ft. south of the aluminum pipe.

This monument as set by Garfield County in 2006, is accepted as the best available evidence of the position of the original 1/4 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

Corner falls on a gradual northwest slope in sagebrush.

N. 88°22.0' E., beginning new measurement.

19.794 Point for the E 1/16 section corner of sections 19 and 30.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:

Deposit a magnet enclosed in a plastic case at the base of the aluminum post.

Set a steel fence post alongside the aluminum post.

Raise a small mound of stone west of the aluminum post.

Corner falls on west side of main dirt road, on flat ground in sagebrush.

- 29.691 Point for the E-E 1/64 section corner of sections 19 and 30, not monumented.
- 39.588 The corner of sections 19, 20, 29, and 30, monumented with a U.S. Forest Service Survey monument, an iron post, 2 inches diameter, firmly set, projecting 6 inches above the ground, with brass cap marked:

Dependent Resurvey of a Portion of the Subdivisional Lines, Township 34 South, Range 5 West, Salt Lake Meridian, Utah.

CHAINS

USFS T34SR5W VHS LS 4266 UT S19 S20 S30 S29 1977

Found a steel fence post 1 ft. west of the iron post.

Corner falls on flat ground under power line.

This monument as set by the U.S. Forest Service in 1977, is accepted as the best available evidence of the position of the original section corner.

- S. $0^{\circ}17.7'$ W., between sections 29 and 30.
- 10.064 Point for the N-N 1/64 section corner of sections 29 and 30.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with aluminum cap marked:

N-N 1/64 S30|S29 2008

Deposit a magnet enclosed in a plastic case at the base of the aluminum post.

Set a steel fence post alongside the aluminum post.

From this corner point, a rebar, 5/8 inch diameter, with yellow cap marked: RLS 164561, bears N. $44^{\circ}09.0'$ W., 0.034 chains distance.

20.128 The N 1/16 section corner of sections 29 and 30, monumented with a Talbot Land Surveying monument, an aluminum pipe, 2 1/2 inches diameter, firmly set, projecting 4 inches above the ground, with a 3 1/4 inches diameter aluminum cap marked:

Talbot Land Surveyors T34SR5W N 1/16 S30 | S29 2000 RPLS 165634

This monument as set by Lanny Talbot in 2000, is accepted as a faithful establishment of the position of the N 1/16 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

CHAINS

Corner falls in an N-S fence line on a gentle south slope, under a power line.

- S. 0°18.1′ W., beginning new measurement.
- 10.059 The S-N 1/64 section corner of sections 29 and 30, monumented with a Talbot Land Surveying monument, a rebar, 5/8 inch diameter, firmly set, projecting 2 inches above the ground, with a 3 1/4 inches diameter aluminum cap marked:

Talbot Land Surveyors T34SR5W S-N 1/64 S30|S29 2000 RPLS 165634

This monument as set by Lanny Talbot in 2000, is accepted as a faithful establishment of the position of the S-N 1/64 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

From this corner, a rebar, 5/8 inch diameter, firmly set, with a yellow cap marked, PLS 162522, bears N. $41^{\circ}31.0'$ W., 0.096 chains distance.

Corner falls in old N-S fence line.

- S. 0°18.0" W., beginning new measurement.
- 10.063 The 1/4 section corner of sections 29 and 30, monumented with a Talbot Land Surveying monument, an aluminum pipe, 2 inches diameter, firmly set, flush with oiled road, with a 3 1/4 inches diameter aluminum cap marked:

Talbot Land Surveyors T34SR5W 1/4 S30|S29 2000 RPLS 165634

This monument as set by Lanny Talbot in 2000, is accepted as the best available evidence of the position of the original 1/4 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

From this corner point, a rebar, 5/8 inch diameter, projecting 6 inches above the ground, with red cap marked: Lanny Talbot RPLS

CHAINS

165634, this functions as the NW corner of Parcel "A", in section 29, bears S. 0°11.1′ W., 0.261 chains distance. From this corner point, a rebar, 5/8 inch diameter, projecting 4 inches above the ground, with yellow cap marked: RLS 4876, bears S. 3°53.8′ E., 0.258 chains distance.

Corner falls south of centerline of a E-W oiled road.

From this corner, a U.S. Forest Service Survey monument, a brass cap 3 ins. diam., buried 7 inches below road surface, with illegible marks, bears N. 8°54.7′ E., 0.096 chains distance. I reject this corner as the 1/4 section corner of sections 29 and 30, due to the evidence of glass and metal found in the area, supporting the testimony of local residents stating the area had been used as a trash dump for many years before this corner was set in 1977. Also the position of the Talbot monument is more harmoniously related to the 1924 Nelson survey.

S. 0°35.6′ W., beginning new measurement.

20.027 The S 1/16 section corner of sections 29 and 30, monumented with a Talbot Land Surveying monument, an aluminum pipe, 2 inches diameter, firmly set, in a steel pipe 3 inches diameter, with a 3 1/4 inches diameter aluminum cap marked:

This monument as set by Lanny Talbot in 2000, is accepted as a faithful establishment of the position of the S 1/16 section corner.

Found a steel fence post alongside the aluminum pipe.

Corner falls 6 ft. east of a N-S oiled road.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

S. 0°33.9′ W., beginning new measurement.

20.021 The corner of sections 29, 30, 31, and 32, monumented with a U.S. Forest Service Survey monument, an iron post, 2 inches diameter, firmly set, flush with dirt road, with brass cap marked:

CHAINS

USFS T34SR5W VHS LS 4266 UT S30 S29 S31 S32 1977

This monument as set by the U.S. Forest Service in 1977, is accepted as the best available evidence of the position of the original section corner.

Corner falls in 4-wheeler trail, and 11 ft. south of corner of fences, projecting east and north, also serving as north side of corral chute, and 12 ft. north of corner of fences, projecting south and east.

From the corner of sections 25, 30, 31, and 36, on the west boundary of the township, hereinbefore described.

- N. 89°22.2' E., between sections 30 and 31.
- 4.429 Intersect the west boundary of Tract 37, between corners 2 and 3, not monumented.
- 19.402 The W 1/16 section corner of sections 30 and 31, monumented with an iron post, 1 inch diameter, firmly set, flush with ground surface, with brass cap marked as described in the 1924 resurvey.

No remaining evidence of the 1924 bearing trees were found.

Set a steel fence post alongside the iron post.

This corner is located on line 1-4 of Tract 37.

Corner falls in open meadow.

- N. 89°28.6' E., beginning new measurement.
- 19.954 The 1/4 section corner of sections 30 and 31, monumented with an iron post, 1 inch diameter, firmly set, in a mound of stone, with brass cap marked as described in the 1924 resurvey.

No remaining evidence of the 1924 bearing tree was found.

Found a steel fence post alongside the iron post.

Corner falls in open meadow.

- N. 89°27.2' E., beginning new measurement.
- 19.944 The E 1/16 section corner of sections 30 and 31, monumented with a Talbot Land Surveying monument, an aluminum pipe, 2 1/2 inches

CHAINS

diameter, firmly set, projecting 2 inches above the ground, with a $3 \times 1/4$ inches diameter aluminum cap marked:

Found a steel fence post alongside the aluminum pipe.

This monument as set by Lanny Talbot in 2000, is accepted as a faithful establishment of the position of the E 1/16 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

Corner falls in open meadow.

N. 89°26.7' E., beginning new measurement.

19.947 The corner of sections 29, 30, 31, and 32.

Reestablishment of the Survey Executed By T.C. Bailey and J.G. Burrill in 1874.

From the corner of sections 19, 20, 29, and 30.

N. $0^{\circ}07.9'$ E., between sections 19 and 20.

40.047 The 1/4 section corner of sections 19 and 20, monumented with a Talbot Land Surveying monument, an aluminum pipe, 2 inches diameter, firmly set, projecting 4 inches above the ground, with a 3 1/4 inches diameter aluminum cap marked:

Talbot Land Surveyors T34SR5W 1/4 S19|S20 2003 RPLS 165634

Found a steel fence post 1 ft. west of the aluminum pipe.

This monument as set by Lanny Talbot in 2003, is accepted as the best available evidence of the position of the original 1/4 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

CHAINS

Corner falls 1.8 ft. west of corner of fences projecting north and east.

N. 0°24.3' E., beginning new measurement.

39.986 The corner of sections 17, 18, 19, and 20, monumented with a Talbot Land Surveying monument, an aluminum pipe, 2 inches diameter, firmly set, projecting 4 inches above the ground, with a 3 1/4 inches diameter aluminum cap marked:

This monument as set by Lanny Talbot in 2001, is accepted as the best available evidence of the position of the original section corner.

The corner is located at the corner of fences extending N, S, E and $\mbox{W}.$

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

From this corner, the National Geodetic Station "Panguitch" monumented with a standard U.S.G.S. tablet stamped PANGUITCH, cemented in a rock, bears, S. 49°14′05″ E. (FWD), N. 49°12′26″ W. (BACK), 260.165 chains distance.

From the garror of godtions 12 10 10 and 24 on the west bounds

From the corner of sections 13, 18, 19, and 24, on the west boundary of the township, hereinbefore described.

N. $88^{\circ}49.4'$ E., between sections 18 and 19.

39.212 Point for the 1/4 section corner of sections 18 and 19, at proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 22 inches in the ground, to solid rock, with aluminum cap marked:

Deposit a magnet enclosed in a plastic case at the base of the aluminum post.

CHAINS

Set a steel fence post alongside the aluminum post.

Corner falls on a gradual northeast slope in old cutting area.

78.970 The corner of sections 17, 18, 19, and 20.

The Dependent Resurvey of a portion the Subdivision of Section 30, T. 34 S., R. 5 W., Salt Lake Meridian, Utah.

Reestablishment of the Survey Executed by A. Nelson in 1924.

From the 1/4 section corner of sections 30 and 31.

N. $0^{\circ}40.7'$ E., on the N-S centerline of section 30.

19.807 The center S 1/16 section corner of section 30, monumented with a Garfield County Survey monument, an aluminum pipe, 2 inches diameter, firmly set, projecting 2 inches above the ground with a 3 1/4 inches diameter aluminum cap marked:

Garfield County
T34SR5W
C
S 1/16 | S30
C
2006
PLS 161040

Found a steel fence post alongside the aluminum post.

Found a mound of stone 3 ft. by 3 ft. base by 3 ft. high, south of the aluminum pipe.

This monument as set by Garfield County in 2006, is accepted as the best available evidence of the position of the original center S 1/16 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

Corner falls 21.5 ft. south of an E-W fence line, on a gradual east slope in piñon.

N. 0°39.7' E., beginning new measurement.

19.787 The center 1/4 section corner of section 30, monumented with a Garfield County Survey monument, an aluminum pipe, 2 inches diameter, firmly set, projecting 3 inches above the ground, in an embedded mound of stone, with a 3 1/4 inches diameter aluminum cap marked:

CHAINS

Garfield County
T34SR5W
C 1/4
S30
2006
PLS 161040

Found a steel fence post 1 ft. east of the aluminum pipe.

This monument as set by Garfield County in 2006, is accepted as the best available evidence of the position of the original center 1/4 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

- N. 0°39.7' E., beginning new measurement.
- 19.981 Point for the center N 1/16 section corner of section 30, not monumented.
- 39.962 The 1/4 section corner of sections 19 and 30.

From the 1/4 section corner of sections 25 and 30, on the west boundary of the township, hereinbefore described.

- N. $88^{\circ}47.8'$ E., on the E W centerline of section 30.
- 19.624 The center W 1/16 section corner of section 30, monumented with a lava stone, 16x12x5 inches, firmly set, marked with an X on top.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 22 inches in the ground, to solid rock, in a mound of stone, 3 ft. base, to top, with aluminum cap marked:

W 1/16 C — C S30 2008

Deposit the marked stone alongside the aluminum post.

Deposit a magnet enclosed in a plastic case at the base of the aluminum post.

Set a steel fence post alongside the aluminum post.

Corner falls on flat ground in sagebrush.

CHAINS

- N. 88°45.2' E., beginning new measurement.
- 20.129 The center 1/4 section corner of section 30.
 - N. 88°47.5' E., beginning new measurement.
- 19.918 The center E 1/16 section corner of section 30, monumented with a Talbot Land Surveying monument, an aluminum pipe, 2 inches diameter, firmly set, projecting 2 inches above the ground, with a 3 1/4 inches diameter aluminum cap marked:

Found a steel fence post alongside the aluminum pipe.

This monument as set by Lanny Talbot in 2000, is accepted as a faithful establishment of the position of the center E 1/16 section corner.

A Corner Perpetuations and Filing Record are found in the Garfield County Recorder's Office.

From this corner point, a rebar, 5/8 inch diameter, with yellow cap marked: RLS 162522, bears N. $48^{\circ}33.4'$ W., 0.111 chains distance.

Corner falls in old E-W fence line, and 15 ft. south of an E-W oiled road.

- N. 88°47.5′ E., beginning new measurement.
- 9.958 The center E-E 1/64 section corner of section 30, monumented with a rebar, 5/8 inch diameter, firmly set, bent 45 degrees to ground surface, with no cap. Point tied in at bend of rebar.

This monument as set by Lanny Talbot in 2000, is accepted as a faithful establishment of the position of the center E-E 1/64 section corner.

Corner falls 12 ft. south of E-W oiled road.

- N. 88°48.3′ E., beginning new measurement.
- 9.959 The 1/4 section corner of sections 29 and 30.

CHAINS

From the W 1/16 section corner of sections 30 and 31.

N. $0^{\circ}25.6'$ E., on the N-S centerline of the SW 1/4 of section 30.

- 6.249 Corner No. 4 of Tract 37; hereinafter described.
- 19.675 The SW 1/16 section corner, monumented with a Garfield County Survey monument, an aluminum pipe, 2 inches diameter, firmly set, projecting 2 inches above the ground with a 3 1/4 inches diameter aluminum cap marked:

Garfield County T34SR5W SW 1/16 S30 2006 PLS 161040

Found a steel fence post alongside the aluminum pipe.

This monument as set by Garfield County in 2006, is accepted as the best available evidence of the position of the original SW 1/16 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

Corner falls on flat ground in piñon.

N. 0°25.1′ E., beginning new measurement.

19.661 The center W 1/16 section corner of section 30.

From the S 1/16 section corner of sections 25 and 30, on the west boundary of the township, hereinbefore described.

- N. $89^{\circ}05.6'$ E., on the E-W centerline of the SW 1/4 of section 30.
- 19.516 The SW 1/16 section corner of section 30.

- N. 89°06.3' E., beginning new measurement.
- 20.043 The center S 1/16 section corner of section 30.

The Retracement of Tract 37 in the SW 1/4 of the SW 1/4 of Section 30, and in the NW 1/4 of the NW 1/4 of Section 31, T. 34 S., R. 5 W., Salt Lake Meridian, Utah.

THE RETRACEMENT OF TRACT 37,
TOWNSHIP 34 SOUTH, RANGE 5 WEST, SALT LAKE MERIDIAN, UTAH.

CHAINS

Reestablishment of the Survey Executed by A. Nelson in 1924.

From the W 1/16 section corner of sections 30 and 31.

- S. $0^{\circ}04.7'$ E., on east boundary of Tract 37, identical with a portion of the N-S centerline of the NW 1/4 of section 31.
- 6.250 Corner No. 1 of Tract 37, monumented with an iron post, 1 inch diameter, firmly set, projecting 12 inches above the ground, with brass cap marked as described in the 1924 survey.

from which the 1924 bearing tree

A piñon, dead and standing, 12 ins. diam., bears N. 62° W., 32 links distance, with scribe marks COR 1 BT visible on a partially healed blaze.

Set a steel fence post alongside the iron post.

Corner falls on a north facing slope in piñon and juniper growth.

- S. 89°59.3′ W., on the south boundary of Tract 37.
- 15.002 Corner No. 2 of Tract 37, monumented with an iron post, 1 inch diameter, firmly set, in a mound of stone, with brass cap marked as described in the 1924 survey.

No remaining evidence of the original bearing tree was found.

Set a steel fence post alongside the iron post.

Corner falls in a N-S fence line, at the foot of a north facing slope.

- N. 0°12.2' E., on the west boundary of Tract 37.
- 6.088 Intersect the line between sections 30 and 31.
- 12.447 Corner No. 3 of Tract 37, monumented with an iron post, loosely set, I therefore tie off the original bearing tree.
 - A piñon, 16 ins. diam., bears S. 64° E., 72 links distance, with visible scribe marks on an open blaze. (Record; S. $65 \ 1/4^{\circ}$ E.)

Reset iron post in place, in a mound of stone 4 ft. by 4 ft. base by 3 ft. high, to top, with brass cap marked as described in the 1924 survey.

N. 89°47.4' E., on the north boundary of Tract 37.

THE RETRACEMENT OF TRACT 37,
TOWNSHIP 34 SOUTH, RANGE 5 WEST, SALT LAKE MERIDIAN, UTAH.

CHAINS

15.002 Corner No. 4 of Tract 37, at the intersection with the N-S centerline of the SW 1/4, monumented with an iron post, 1 inch

diameter, firmly set, projecting 10 inches above the ground, with brass cap marked as described in the 1924 survey.

No remaining evidence of the original bearing tree was found.

Set a steel fence post alongside the iron post.

Corner falls on a south facing slope, at edge of tree line.

- S. $0^{\circ}25.6'$ W., on east boundary of Tract 37 identical with a portion of the N-S centerline of the SW 1/4 of section 30.
- 6.249 The W 1/16 section corner of sections 30 and 31 and the point of beginning.

The Subdivision of Section 30 T. 34 S., R. 5 W., Salt Lake Meridian, Utah.

From the center E 1/16 section corner of section 30.

- N. 0°28.9' E., on the N-S centerline of the NE 1/4 of section 30.
- 10.025 The center S-NE 1/64 section corner of section 30, monumented with a Talbot Land Surveying monument, a rebar, 5/8 inch diameter, firmly set, projecting 2 inches above the ground, with a 3 1/4 inches diameter aluminum cap marked:

Talbot Land Surveyors
T34SR5W
S30
C-S-NE
1/64
S30
2000
RPLS 165634

This monument as set by Lanny Talbot in 2000, is accepted as a faithful establishment of the position of the center S-NE 1/64 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

From this corner point, a rebar 5/8 inch diameter, with yellow cap marked RLS 162522, bears N. $45^{\circ}03.6'$ W., 5.16 ft. distance.

Corner falls on top of small ridge in sagebrush.

CHAINS

- N. 0°28.8' E., beginning new measurement.
- 10.026 The NE 1/16 section corner, of section 30, monumented with a Talbot Land Surveying monument, an aluminum pipe, 2 1/2 inches diameter, firmly set, projecting 4 inches above the ground, with a 3 1/4 inches diameter aluminum cap marked:

Talbot Land Surveyors T34SR5W NE 1/16 S30 2000 RPLS 165634

Found a steel fence post alongside the aluminum pipe.

This monument as set by Lanny Talbot in 2000, is accepted as a faithful establishment of the position of the NE 1/16 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

Corner falls on flat ground in sagebrush.

N. 0°28.7′ E., beginning new measurement.

- 10.027 Point for the center N-NE 1/64 section corner of section 30, not monumented.
- 20.054 The E 1/16 section corner of sections 19 and 30.

From the N 1/16 section corner of sections 29 and 30.

- S. 88°36.3' W., on the E-W centerline of the NE 1/4 of section 30.
- 9.930 The center E-NE 1/64 section corner of section 30, monumented with a Talbot Land Surveying monument, an aluminum pipe, 2 1/2 inches diameter, firmly set, projecting 3 inches above the ground, with a 3 1/4 inches diameter aluminum cap marked:

Talbot Land Surveyors
T34SR5W
S30
C-E-NE
1/64
2000
RPLS 165634

This monument as set by Lanny Talbot in 2000, is accepted as a faithful establishment of the position of the center E-NE 1/64 section corner.

CHAINS

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

Corner falls on west edge of the cut bank for the west fence line of the Garfield County Jail, on flat ground in sagebrush.

S. 88.34.9' W., beginning new measurement.

9.928 The NE 1/16 section corner of section 30.

S. 88°34.9′ W., beginning new measurement.

19.856 The point for the center N 1/16 section corner of section 30.

From the center E-NE 1/64 section corner of section 30.

 $N.~0^{\circ}23.6'~E.,$ on the N-S centerline of the NE 1/4 of the NE 1/4 of section 30.

10.043 Point for the NE-NE 1/64 section corner, at intersection with the E-W centerline of the NE 1/4 of the NE 1/4 of section 30.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:

NE-NE 1/64 \$30 2008

Deposit a magnet enclosed in a plastic case at the base of the aluminum post.

Set a steel fence post alongside the aluminum post.

From this corner point, a rebar, 5/8 inch diameter, with yellow cap marked: RLS 164561, bears N. $35^{\circ}02.6'$ W., 0.031 chains distance.

Corner falls on flat ground in sagebrush.

20.088 The point for the E-E 1/64 section corner of sections 19 and 30.

From the N-N 1/64 section corner of sections 29 and 30.

 $S.~88^{\circ}28.5'$ W., on the E-W centerline of the NE 1/4 of the NE 1/4 of section 30.

- 9.912 The NE-NE 1/64 section corner of section 30.
- 19.824 The point for the center N-NE 1/64 section corner of section 30.

From the center E-E 1/64 of section 30.

CHAINS

- $N.~0^{\circ}23.1'$ E., on the N-S centerline of the SE 1/4 of the NE 1/4 of section 30.
- 10.043 The SE-NE 1/64 section corner, at intersection with the E W centerline of the SE 1/4 of the NE 1/4 of section 30, monumented with a Talbot Land Surveying monument, rebar, 5/8 inch diameter, firmly set, with a 3 1/4 inches diameter aluminum cap marked:

Talbot Land Surveyors
T34SR5W
S30
SE-NE 1/64
2000
RPLS 165634

This monument as set by Lanny Talbot in 2000, is accepted as a faithful establishment of the position of the SE-NE 1/64 section corner.

The Corner Perpetuation and Filing Records are found in the Garfield County Recorder's Office.

From this corner point, a rebar, 5/8 inch diameter, with yellow cap marked: RLS 164561, bears N. $39^{\circ}25.9'$ W., 0.083 chains distance.

From this corner point, a rebar, 5/8 inch diameter, with yellow cap marked: 162322, bears N. $52^{\circ}35.7'$ W., 0.091 chains distance.

Corner falls on flat ground in sagebrush.

y y

N. 0°23.3' E., beginning new measurement.

10.045 The center E-NE 1/64 section corner of section 30.

From the S-N 1/64 section corner of sections 29 and 30.

 $\mathbf{S.~88^{\circ}41.5^{\prime}~W.}$, on the E-W centerline of the SE 1/4 of the NE 1/4 of section 30.

- 9.945 The SE-NE 1/64 section corner of section 30.
 - S. 88°41.2' W., beginning new measurement.
- 9.942 The center S-NE 1/64 of section 30.

From the E 1/16 section corner of sections 30 and 31.

- $N.~0^{\circ}37.5'$ E., on the N-S centerline of the SE 1/4 of section 30.
- 19.916 Point for the SE 1/16 section corner, at intersection with the E-W centerline of the SE 1/4 of section 30.

CHAINS

Set an aluminum post, 30 inches long, $2\ 1/2$ inches diameter, 15 inches in the ground, to solid rock, in a mound of stone, 3 ft. base to top, with aluminum cap marked:

SE 1/16 S30 2008

Deposit a magnet enclosed in a plastic case at the base of the aluminum post.

Set a steel fence post alongside the aluminum post.

From this corner point, a Talbot Land Surveying monument, bears, S. 13°07.8′ E., 0.339 chains distance; an aluminum pipe, 2 inches diameter, firmly set, projecting 4 inches above the ground, with a 3 1/4 inches diameter aluminum cap marked:

Talbot Land Surveyors
SE 1/16 S30
2000
RPLS 165634

Corner falls on a gradual open northeast slope.

39.831 The center E 1/16 section corner of section 30.

Form the S 1/16 section corner of sections 29 and 30.

- S. 89°08.2' W., on the E-W centerline of the SE 1/4 of section 30.
- 19.931 The SE 1/16 section corner of section 30.
- 39.859 The center S 1/16 section corner of section 30.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FIELD ASSISTANTS

Name	Capacity
Ron Baugh	Cadastral Surveyor

CERTIFICATE OF SURVEY

I, Jeremy D. Davis, Cadastral Surveyor, hereby certify upon honor, that in pursuance of special instructions bearing the date of the 8th day of August, 2008, I have executed a dependent resurvey of a portion of the west boundary, a portion of the subdivisional lines, a portion of the subdivision of section 30, the retracement of Tract 37, and the subdivision of a portion of section 30, in Township 34 South, Range 5 West, of the Salt Lake Meridian, in the State of Utah, which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said special and supplemental special instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in specific manner described in the foregoing field notes.

Feb 2, 2010
Date

adastra Surveyor

CERTIFICATE OF APPROVAL

BUREAU OF LAND MANAGEMENT Salt Lake City, Utah

The following field notes of the dependent resurvey of a portion of the west boundary, a portion of the subdivisional lines, a portion of the subdivision of section 30, the retracement of tract 37, and the subdivision of a portion of section 30, in Township 34 South, Range 5 West, Salt Lake Meridian, Utah, executed by Jeremy D. Davis, Cadastral Surveyor having been critically examined and found correct, are hereby approved.

February 22, 2010

Chief Cadastral Surveyor for Utah